Date: 2021.03.12

Scanning Laser Range Finder Smart-URG Pro UST-30LC Specification

C € RoHS

Symbol	Amended Reason			Pages	Date	Amended by	Ref.No	
Approved by	Checked by	Drawn by	Designed by	Title	UST-30LC Specification			
M.Hino	A.Yamamoto	T.Kasahara	A.Yamamoto	Drawing No.		C-42-04468		1/13

1. General

UST-30LC is a sensor which scans a 270° field using a laser beam (λ = 905 nm), then calculates coordinates by measuring the distance to an object and its corresponding step angle (LX mode) and detects obstacles within the setting area (LA mode). Only LX mode supports the multi echo data output. In LA mode, selected single echo output data is available. The desired mode (LX or LA) can be selected in the configuration application.

1-2. Area configuration

The user can configure areas in the sensor using application software provided by the manufacturer. Install the software in a supported operating system and connect the sensor using an Ethernet cable. See section 7 for details on types of area configuration.

1-3. Area switching


The sensor has 5 external inputs for switching the area. Provide the correct signal states on these inputs (see Table 1) to switch the area. There are modes 1 and 2 in LA mode. Use mode 2 when using the motor synchronization function. However, the number of areas that can be set decrease.

1-4. Malfunction output


The sensor has a self-diagnostic function. It switches the malfunction output to an OFF state when errors are detected in the internal components.

2. Structure

2-1.Strucure diagram



2-2. Laser scanning image



3. Important notes

- (1) This sensor is not a safety device/tool.
- (2) This sensor cannot be used for human body detection as per the machinery directives.
- (3) Hokuyo products are not developed and manufactured for the use in weapons, equipments or related technologies intended for destroying human lives or causing mass destruction. If such possibilities or usages are revealed, the sales of Hokuyo products to those customers might be halted by the laws of Japan such as Foreign Exchange Law, Foreign Trade Law or Export Trade control order. In addition, Hokuyo products are for the purpose of maintaining the global peace and security in accordance with the above law of Japan.
- (4) Sensor emits laser for measurement. Sensor's operation may become unstable under the influence of strong interference light or when emitted lights are not reflected back from the object.
- (5) Sensor's operation may become unstable due to rain, snow and fog or due to dust pollution on the optical window.
- (6)Rules and regulations related to safety should be followed strictly when machine users and system designers operates the sensor.
- (7)Before using the sensor, please read carefully and understand this specification.

4. Specifications

Specifications						
Product name	Scanning Laser Range Finder					
Model	UST-30LC					
Supply voltage	12VDC/	24VDC (operation range 10 to 30V ripple within 10%)				
Cumply oursent(*1)	150mA	or less (when using DC24V)				
Supply current(*1)	(during s	start up 450mA is necessary.)				
Supply power	Less that	Less than 3.6 W(steady state)				
Light source	Laser sea	Laser semiconductor (905nm)				
Laser Safety	Class1 (Class1 (IEC60825-1:2014)				
	0.05m to	30m(*2) (white kent sheet)				
Detection range		12m(*2) (diffuse reflectance 10%)				
and object		tection distance: 60m				
	Min. de	etection size :90mm(10m), 180mm(20m), 260mm(30m)				
Accuracy	±40mm	(*2)				
Repeated accuracy	σ< 20mr	n (*2)				
Scan angle	270°					
Scan speed(*3)	25msec	(motor speed 2400rpm)				
Angular resolution	0.125°					
Start up time	Within 1	0 sec (start up time differs if malfunction is detected during start up)				
•	Photo-coupler, open collector output Max DC 30V 50mA					
	Output 1: Output 1 OFF during object detection					
	Output 2: Output 2 OFF during object detection					
Outputs	Output 3: Output 3 OFF during object detection					
	Malfunction output: ON during normal operation, OFF during malfunction					
	Synchronous output: Synchronization signal during Master/Slave operation.					
	Note: Output 1 to 3 are switched OFF during malfunction state					
Inputs	Photo-coupler, common cathode, power supply is 4mA when input is ON					
Inputs	Input 1 to 5: Area switching inputs (refer Table1)					
Output response time	OFF	66msec to 3241msec				
(*4)	ON	66msec to 3241msec				
Interface		100BASE-TX				
	LX mod	e				
	Power supply LED display (blue): Blinks during start up and malfunction state.					
	LA mode					
LED display	Blue LED: ON during normal operation, blink during the start up, configuration					
LLD display	and malfunction state					
	Orange LED 1: Output 1 ON during object detection					
	Orange LED 2: Output 2 ON during object detection					
		LED 3: Output 3 ON during object detection				
		nization Master/Slave operation mode (can set by using Area Designer)				
Synchronization	_	nization slave $mode(0^{\circ})$				
function (*5)		nization slave $mode(90^{\circ})$				
		nization slave mode(180°)				
	Synchronization slave mode(270°)					

Title	UST-30LC Specification	Drawing No	C-42-04468	4/13
-------	------------------------	------------	------------	------

. Specifications				
Surrounding intensity	Less than 100,000lx Note: Avoid direct sunlight or other illumination sources as it may cause sensor malfunction			
Ambient temperature and humidity				
Storage temperature and humidity	-30°C to +70°C, below 85%RH (without dew, frost)			
Vibration resistance	10 to 55Hz double amplitude of 1.5mm for 2hrs in each X, Y, and Z direction 55 to 200Hz 98m/s ² sweep of 2min for 1hr in each X,Y and Z direction			
Shock resistance	196m/s ² (20G) X,Y and Z direction each 10 times			
Insulation resistance	10 M Ω			
EMC standards	(EMI) EN61326-1:2013 EN55011:2009 + A1:2010 (EMS) EN61326-1:2013 EN61000-4-2:2009 EN61000-4-3:2006 + A1:2008 + A2:2010 EN61000-4-6:2014 EN61000-4-8:2010			
RoHS	(EU)2015/863			
Protective Structure	IP67(*6)			
Weight	130g (excluding cable)			
Material	Front case: Polycarbonate, Rear case: Aluminum			
Dimensions(W×D×H) $50\times50\times70$ mm (sensor only)				

- (*1) Please use a power supply with enough current capacity.
- (*2) Under the factory standard testing conditions using white kent sheet.

 In the low temperature environment of -11°C or below, the detection distance will be as below. white kent sheet: 0.05m to 25m, diffuse reflectance 10%: 0.05m to 8m
- (*3) In the case of using other command than MD,MS and ME. There is possibility of delay in response speed, due to surrounding environment.
- (*4)Initial setting is 66msec. ON/OFF delay function switching is possible by Area Designer. Response time can be further delayed by a maximum of 1scan during the area switching.
- (*5)Initial setting is synchronization master. When using synchronization operation, refer to section 9 for details about synchronization wiring. Synchronization slave setting is possible using Area Designer.
- (*6)The protective structure of Ethernet and Power connector is not IP67.

Table 1: Input states and corresponding area number					
[Input 1]	[Input 2]	[Input 3]	[Input 4]	[Input 5]	Area Number*2
ON	ON	ON	ON	ON	Laser off*1
OFF	ON	ON	ON	ON	Area1
ON	OFF	ON	ON	ON	Area2
OFF	OFF	ON	ON	ON	Area3
ON	ON	OFF	ON	ON	Area4
OFF	ON	OFF	ON	ON	Area5
ON	OFF	OFF	ON	ON	Area6
OFF	OFF	OFF	ON	ON	Area7
ON	ON	ON	OFF	ON	Area8
OFF	ON	ON	OFF	ON	Area9
ON	OFF	ON	OFF	ON	Area10
OFF	OFF	ON	OFF	ON	Area11
ON	ON	OFF	OFF	ON	Area12
OFF	ON	OFF	OFF	ON	Area13
ON	OFF	OFF	OFF	ON	Area14
OFF	OFF	OFF	OFF	ON	Area15
ON	ON	ON	ON	OFF	Area16
OFF	ON	ON	ON	OFF	Area17
ON	OFF	ON	ON	OFF	Area18
OFF	OFF	ON	ON	OFF	Area19
ON	ON	OFF	ON	OFF	Area20
OFF	ON	OFF	ON	OFF	Area21
ON	OFF	OFF	ON	OFF	Area22
OFF	OFF	OFF	ON	OFF	Area23
ON	ON	ON	OFF	OFF	Area24
OFF	ON	ON	OFF	OFF	Area25
ON	OFF	ON	OFF	OFF	Area26
OFF	OFF	ON	OFF	OFF	Area27
ON	ON	OFF	OFF	OFF	Area28
OFF	ON	OFF	OFF	OFF	Area29
ON	OFF	OFF	OFF	OFF	Area30
OFF	OFF	OFF	OFF	OFF	Area31

^{*1:}Laser is switched off when all inputs (1 to 5) are ON.

^{*2:} When using the synchronization function in LA mode 2, the maximum area number will be 15.

5. Connection


5-1. Power source, I/O cable

connector: DF62B-24EP-2.2C(00) Hirose


Cable length: 1000mm

Keep the output wires open or connect to output "Com Output +" if not in use. Keep the input wires open or connect to output "Com Input -" if not in use.


The input and output directions are based on this product.



Short point 1:



Short point 2:



Number	Color	Signal	
1	Orange(Red short point 1)	+VIN (DC12V/DC24V)	
2	Orange(Black short point 1)	-VIN	
3	Gray(Red short point 1)	Output 1	
4	Gray(Black short point 1)	Output 2	
5	White(Red short point 1)	Output 3	
6	White(Black short point 1)	Malfunction output	
7	Yellow(Red short point 1)	Synchronous output	
8	Yellow(Black short point 1)	COM Input -	
9	Pink(Red short point 1)	COM Output +	
10	Pink(Black short point 1)	Input 1	
11	Orange(Red short point 2)	Input 2	
12	Orange(Black short point 2)	Input 3	
13	Gray(Red short point 2)	Input 4	
14	Gray(Black short point 2)	Input 5/ Synchronous input	
15	NC	NC	
16	NC	NC	
17	NC	NC	
18	NC	NC	
19	NC	NC	
20	NC	NC	
21	NC	NC	
22	NC	NC	
23	NC	NC	
24	NC	NC	

5-2. Ethernet cable

Cable length: 300mm

Color	Signal
White(Orange)	TX+
Orange	TX-
White(Green)	RX+
Green	RX-

Title	UST-30LC Specification	Drawing No	C-42-04468	7/13
-------	------------------------	------------	------------	------

6. LED display Power supply display

7. Area configuration

7-1 Normal configuration

Output 3

In the normal configuration, the area for Output 1 is configured first and the shape of it can be configured freely. Areas for Output 2 and Output 3 are dependent on the set area of Output 1 and therefore they are configured inside it. The shapes of Output 2 and Output 3 areas can be straight, fan shape or ratio (Figure 1).

Figure 2 and Table 2 show the relationship between the detected object position and the output states.

Output 1

Output 2




Figure 1: Normal area configuration




Figure 2: Output areas

Object position	Output 1	Output 2	Output 3
A	OFF	ON	ON
В	OFF	OFF	ON
С	OFF	OFF	OFF

Table 2: Relationship between object position and output states

(Blinks during start up and malfunction state)

Title	UST-30LC Specification	Drawing No	C-42-04468	8/13
-------	------------------------	------------	------------	------

7-2. Independent configuration

In the independent configuration, areas for Output 1, Output 2 and Output 3 can be configured freely. The field covered by each output can be completely separate from the other output areas or there can be an overlapping region between the output areas Figure 3 (a) and (b).

Figure 4 and Table 3 show the relationship between the object position and the output states.




Figure 3: Independent area configuration





Figure 4: Output areas

Object position	Output 1	Output 2	Output 3
A	OFF	ON	ON
В	ON	OFF	ON
С	ON	ON	OFF
D	OFF	OFF	ON
Е	OFF	ON	OFF
F	ON	OFF	OFF
G	OFF	OFF	OFF

Table 3: Relationship between object position and output area



Drawing No


C-42-04468

10/13

UST-30LC Specification

Title

9. The example of Synchronous wiring



Note: This function is available in LA mode 2.

Title UST-30LC Specification Drawing No C-42-04468 11/13


10. Measurement Data

Distance Value (x)	Meaning
x < 10	Output numerical number "65534" as Measurement error
$10 \le x \le 60000$	Valid distance [mm]
x > 60000	Output numerical number "65533" as Measurement error (object does not exists or object has low reflectivity)

11. Control signal

11-1. Synchronous output

1 pulse is approximately 1ms. Output signal synchronization timing chart is shown as below.



12. Multi-echo function

This sensor provides a maximum of three echo $(1^{st}, 2^{nd}, last)$ for each step (one direction). It also provides distance value and level value for each step. (For LX mode only)

Multiple echo are generated when the laser beam is split by reflection on surface of transparent objects, reflection on object's edge and reflection from small particles such as rain, mist, dust and fog. Thus, distance and level value obtained from the multiple reflections in the same direction is called multi echo. However, if the distance between two object is too close or the object has low reflectance, the sensor may not detect it as multi echo.

Title US	T-30LC Specification	Drawing No	C-42-04468	12/13
----------	----------------------	------------	------------	-------

13. Ethernet Setting

1. The setting value is as below.

IP Initial value :192.168.0.10

Port number :10940

2. About changing IP address

It is possible to change and reset the IP address using a specialized application (IP Discovery).

For details on installation and operation of IP Discovery, Please refer to IP discovery manual. (C-41-02603)

14. Cautions for operation

This sensor uses high speed processing components that generate heat during operation.

The heat is concentrated at the bottom of the unit. When mounting, please attach the bottom of the unit to a good heat sink. A 200mm x 200mm x 2mm aluminum plate is recommended as a heat sink.

If multiple sensors are installed side by side, a sensor might mistake the laser pulses of other units as its own and the detection error occurs. When it happens, usually the error lasts for one or two steps of measurement. Please use software filters to handle this type of error.

Date: 2021.03.12

Scanning Laser Range Finder Smart-URG Pro UST-30LC-X01 Specification

C € RoHS

Symbol	Amended Reason			Pages	Date	Amended by	Ref.No	
Approved by	Checked by	Drawn by	Designed by	Title	UST-30LC-X01			
M.Hino	A.Yamamoto	T.Kasahara	A.Yamamoto	Drawing No.	Specification C-42-04485		1/13	

1. General

UST-30LC-X01 is a sensor which scans a 270° field using a laser beam (λ = 905 nm), then calculates coordinates by measuring the distance to an object and its corresponding step angle (LX mode) and detects obstacles within the setting area (LA mode). Only LX mode supports the multi echo data output. In LA mode, selected single echo output data is available. The desired mode (LX or LA) can be selected in the configuration application.

1-2. Area configuration

The user can configure areas in the sensor using application software provided by the manufacturer. Install the software in a supported operating system and connect the sensor using an Ethernet cable. See section 7 for details on types of area configuration.

1-3. Area switching


The sensor has 4 external inputs for switching the area. Provide the correct signal states on these inputs (see Table 1) to switch the area. There are modes 1 and 2 in LA mode. Use mode 2 when using the motor synchronization function. However, the number of areas that can be set and the number of detection outputs decrease.

1-4. Malfunction output

The sensor has a self-diagnostic function. It switches the malfunction output to an OFF state when errors are detected in the internal components.


2. Structure

2-1.Strucure diagram



2-2. Laser scanning image

Title



UST-30LC-X01 Specification

Drawing No

C-42-04485

3. Important notes

- (1) This sensor is not a safety device/tool.
- (2) This sensor cannot be used for human body detection as per the machinery directives.
- (3) Hokuyo products are not developed and manufactured for the use in weapons, equipments or related technologies intended for destroying human lives or causing mass destruction. If such possibilities or usages are revealed, the sales of Hokuyo products to those customers might be halted by the laws of Japan such as Foreign Exchange Law, Foreign Trade Law or Export Trade control order. In addition, Hokuyo products are for the purpose of maintaining the global peace and security in accordance with the above law of Japan.
- (4) Sensor emits laser for measurement. Sensor's operation may become unstable under the influence of strong interference light or when emitted lights are not reflected back from the object.
- (5) Sensor's operation may become unstable due to rain, snow and fog or due to dust pollution on the optical window.
- (6)Rules and regulations related to safety should be followed strictly when machine users and system designers operates the sensor.
- (7)Before using the sensor, please read carefully and understand this specification.

4. Specifications

Scanning Laser Range Finder		
UST-30LC-X01		
12VDC/24VDC (operation range 10 to 30V ripple within 10%)		
150mA or less (when using DC24V)		
(during start up 450mA is necessary.)		
Less than 3.6 W(steady state)		
Laser semiconductor (905nm)		
Class1 (IEC60825-1:2014)		
0.05m to 30m(*2) (white kent sheet)		
0.05m to 12m(*2) (diffuse reflectance 10%)		
Max. detection distance : 60m		
Min. detection size: 90mm(10m), 180mm(20m), 260mm(30m)		
±40mm (*2)		
σ< 20mm (*2)		
270°		
25msec (motor speed 2400rpm)		
0.125°		
Within 10 sec (start up time differs if malfunction is detected during start up)		
Photo-coupler, open collector output Max DC 30V 50mA		
Output 1: Output 1 OFF during object detection		
Output 2: Output 2 OFF during object detection		
Output 3: Output 3 OFF during object detection / Synchronous output		
Malfunction output: ON during normal operation, OFF during malfunction		
Note: Output 1 to 3 are switched OFF during malfunction state		
Photo-coupler, common cathode, power supply is 4mA when input is ON		
Input 1 to 5: Area switching inputs (refer Table 1)		
OFF 66msec to 3241msec		
ON 66msec to 3241msec		
Ethernet 100BASE-TX		
LX mode		
Power supply LED display (blue): Blinks during start up and malfunction state.		
LA mode		
Blue LED: ON during normal operation, blink during the start up, configuration		
and malfunction state		
Orange LED 1: Output 1 ON during object detection		
Orange LED 2: Output 2 ON during object detection		
Orange LED 3: Output 3 ON during object detection		
Synchronization Master/Slave operation mode (can set by using Area Designer)		
Synchronization slave $mode(0^{\circ})$		
Synchronization slave mode(90°)		
Synchronization slave mode(180°)		
Synchronization slave mode(270°)		

Title	UST-30LC-X01 Specification	Drawing No	C-42-04485	4/13
-------	----------------------------	------------	------------	------

4. Specifications	
	Less than 100,000lx
Surrounding intensity	Note: Avoid direct sunlight or other illumination sources as it may cause sensor malfunction
Ambient temperature and humidity	-30°C to +50°C, below 85%RH (without dew, frost)
Storage temperature and humidity	-30°C to +70°C, below 85%RH (without dew, frost)
Vibration resistance	10 to 55Hz double amplitude of 1.5mm for 2hrs in each X, Y, and Z direction 55 to 200Hz 98m/s ² sweep of 2min for 1hr in each X,Y and Z direction
Shock resistance	196m/s ² (20G) X,Y and Z direction each 10 times
Insulation resistance	10 M Ω
EMC standards	(EMI) EN61326-1:2013 EN55011:2009 + A1:2010 (EMS) EN61326-1:2013 EN61000-4-2:2009 EN61000-4-3:2006 + A1:2008 + A2:2010 EN61000-4-6:2014 EN61000-4-8:2010
RoHS	(EU)2015/863
Protective Structure	ĪP67
Weight	130g (excluding cable)
Material	Front case: Polycarbonate, Rear case: Aluminum
Dimensions(W×D×H)	50×50×70mm (sensor only)

- (*1) Please use a power supply with enough current capacity.
- (*2) Under the factory standard testing conditions using white kent sheet. In the low temperature environment of -11° C or below, the detection distance will be as below. white kent sheet: 0.05m to 25m, diffuse reflectance 10%: 0.05m to 8m
- (*3) In the case of using other command than MD,MS and ME. There is possibility of delay in response speed, due to surrounding environment.
- (*4) Initial setting is 66msec. ON/OFF delay function switching is possible by Area Designer. Response time can be further delayed by a maximum of 1scan during the area switching.
- (*5) Initial setting is synchronization master. When using synchronization operation, refer to section 9 for details about synchronization wiring. Synchronization slave setting is possible using Area Designer.

Title UST-30LC-X01 Specification Drawing No C-42-04485 5/13

Table 1: Input states and corresponding area number

[Input 1]	[Input 2]	[Input 3]	[Input 4]	Area Number*2
ON	ON	ON	ON	Laser off*1
OFF	ON	ON	ON	Area1
ON	OFF	ON	ON	Area2
OFF	OFF	ON	ON	Area3
ON	ON	OFF	ON	Area4
OFF	ON	OFF	ON	Area5
ON	OFF	OFF	ON	Area6
OFF	OFF	OFF	ON	Area7
ON	ON	ON	OFF	Area8
OFF	ON	ON	OFF	Area9
ON	OFF	ON	OFF	Area10
OFF	OFF	ON	OFF	Area11
ON	ON	OFF	OFF	Area12
OFF	ON	OFF	OFF	Area13
ON	OFF	OFF	OFF	Area14
OFF	OFF	OFF	OFF	Area15

^{*1:}Laser is switched off when all inputs (1 to 4) are ON.

^{*2:} When using the synchronization function in LA mode 2, the maximum area number will be 7.

5. Connection

5-1. Power source, I/O cable


connector: M12A-12BMMA-SL7001 Amphenol

Cable length: 150mm


Keep the output wires open or connect to output "Com Output +" if not in use. Keep the input wires open or connect to output "Com Input -" if not in use.

The input and output directions are based on this product

Note: In LA mode2, input 4 is a Synchronous input and output 3 is a synchronous output




Short point 1: [mm]



Pin	Color	Signal
1	Orange(Black short point 1)	-VIN
2	Orange(Red short point 1)	+VIN (DC12V/DC24V)
3	Pink(Black short point 1)	Input 1
4	Orange(Red short point 2)	Input 2
5	Gray(Red short point 1)	Output 1
6	Gray(Black short point 1)	Output 2
7	White(Red short point 1)	Output 3/ Synchronous output
8	White(Black short point 1)	Malfunction output
9	Yellow(Black short point 1)	COM Input -
10	Orange(Black short point 2)	Input 3
11	Gray(Red short point 2)	Input 4/ Synchronous input
12	Pink(Red short point 1)	COM Output +

Short point 2:




5-2. Ethernet cable

connector: C10-765252-4D1 Amphenol

Cable length: 150mm

Pin	Color	Signal
1	White(Orange)	TX+
2	White(Green)	RX+
3	Orange	TX-
4	Green	RX-



mating surface

Title UST-30LC-X01 Specification Drawing No C-42-04485 7/13

Output 3 Output 1 Output 1 Output 1

7. Area configuration

7-1 Normal configuration

In the normal configuration, the area for Output 1 is configured first and the shape of it can be configured freely. Areas for Output 2 and Output 3 are dependent on the set area of Output 1 and therefore they are configured inside it. The shapes of Output 2 and Output 3 areas can be straight, fan shape or ratio (Figure 1).

Figure 2 and Table 2 show the relationship between the detected object position and the output states.




Figure 1: Normal area configuration




Figure 2: Output areas

Object position	Output 1	Output 2	Output 3
A	OFF	ON	ON
В	OFF	OFF	ON
С	OFF	OFF	OFF

Table 2: Relationship between object position and output states

Title	UST-30LC-X01 Specification	Drawing No	C-42-04485	8/13
-------	----------------------------	------------	------------	------

7-2. Independent configuration

In the independent configuration, areas for Output 1, Output 2 and Output 3 can be configured freely. The field covered by each output can be completely separate from the other output areas or there can be an overlapping region between the output areas Figure 3 (a) and (b).

Figure 4 and Table 3 show the relationship between the object position and the output states.




Figure 3: Independent area configuration





Figure 4: Output areas

Object position	Output 1	Output 2	Output 3
A	OFF	ON	ON
В	ON	OFF	ON
С	ON	ON	OFF
D	OFF	OFF	ON
Е	OFF	ON	OFF
F	ON	OFF	OFF
G	OFF	OFF	OFF

Table 3: Relationship between object position and output area


Note: When using synchronization function, the detection output will be only 1 and 2. (LA mode 2)

Title	UST-30LC-X01 Specification	Drawing No	C-42-04485	9/13
-------	----------------------------	------------	------------	------



Title

9. The example of Synchronous wiring



Note: This function is available in LA mode 2.

Title UST-30LC-X01 Specification Drawing No C-42-04485 11/13


10. Measurement Data

Distance Value (x)	Meaning
x < 10	Output numerical number "65534" as Measurement error
$10 \le x \le 60000$	Valid distance [mm]
x > 60000	Output numerical number "65533" as Measurement error (object does not exists or object has low reflectivity)

11. Control signal

11-1. Synchronous output

1 pulse is approximately 1ms. Output signal synchronization timing chart is shown as below.



12. Multi-echo function

This sensor provides a maximum of three echo $(1^{st}, 2^{nd}, last)$ for each step (one direction). It also provides distance value and level value for each step. (For LX mode only)

Multiple echo are generated when the laser beam is split by reflection on surface of transparent objects, reflection on object's edge and reflection from small particles such as rain, mist, dust and fog. Thus, distance and level value obtained from the multiple reflections in the same direction is called multi echo. However, if the distance between two object is too close or the object has low reflectance, the sensor may not detect it as multi echo.

Title	UST-30LC-X01 Specification	Drawing No	C-42-04485	12/13
-------	----------------------------	------------	------------	-------

13. Ethernet Setting

1. The setting value is as below.

IP Initial value :192.168.0.10

Port number :10940

2. About changing IP address

It is possible to change and reset the IP address using a specialized application (IP Discovery).

For details on installation and operation of IP Discovery, Please refer to IP discovery manual. (C-41-02603)

14. Cautions for operation

This sensor uses high speed processing components that generate heat during operation.

The heat is concentrated at the bottom of the unit. When mounting, please attach the bottom of the unit to a good heat sink. A 200mm x 200mm x 2mm aluminum plate is recommended as a heat sink.

If multiple sensors are installed side by side, a sensor might mistake the laser pulses of other units as its own and the detection error occurs. When it happens, usually the error lasts for one or two steps of measurement. Please use software filters to handle this type of error.

Title UST-30LC-X01 Specification Drawing No C-42-04485 13/13